Oil Field Environmental Incident Summary

Incident: 20150711155036 Date/Time of Notice: 07/11/2015 15:50
Responsible Party: Tesoro Corp

Well Operator: SM ENERGY COMPANY

Well Name: BRODERSON 13-35H

Field Name: SIVERSTON Well File #: 19390

Date Incident:7/11/2015Time Incident:08:30Facility ID Number:County:MCKENZIETwp:150Rng:98Sec:35Qtr:

Location Description:

Submitted By: SM Energy Luke Studer Received By:

Contact Person: Mark Glasser

watford city

watford, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile
Distance Nearest Water Well: 1 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 5 Barrels

Brine

Other

Description of Other Released Contaminant:

Truck Diver left bleeder valve open while loading truck.

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

minimal

Areal Extent:

spill was contained within the tank battery dike

Potential Environmental Impacts:

minimal, contaminated soil will be hauled off

Action Taken or Planned:

spill will be remediated, Self closing valves will be installed on load line

Wastes Disposal Location: Nuverra

Agencies Involved:

Updates

Date: 7/13/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on location according to the report. NDIC retains oversight.